FORM MR-AR
(Revised 1/91)

RECEIVED
JAN 1 1 1993
DIVISION OF
OIL GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1-92 To (mo./yr.) 12-92

2. DOGM File Number: ~~HCT/043/004~~

3. Mine Name: Utelite Mine

4. Mineral(s) Mined: Mancos Shale

5. Legal Description (Location of Lands Affected):

N ½ ~~1/4~~, ____ ~~1/4~~, Section 8, Township 15, Range 5E

S ½ ~~1/4~~, SE 1/4, Section 5, Township 15, Range 5E

____1/4, ____1/4, Section ____, Township ____, Range ____

6. Name of Operator or Company: Utelite Corp

7. Permanent Address: PO Box 387
3 ½ miles S. Wanship, Hwy 189
Coalville, Utah 84017

8. Company Representative (or designated operator):

Name: Carsten N. Mortensen

Title: President, General Manager

Address: PO Box 726, Coalville, Utah 84017

Phone: 801-359-8541

☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☑ No ☐

2. If active, how much ore or mineral was mined? 171432 tons

3. How much **new** or **additional acreage** was affected during past year? 5 acres

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Of the new surface disturbances half was overburden being removed and half was the dump area where the overburden was pushed. About 10000 tons of overburden was moved.

5. How much acreage was **reclaimed** during past year? none

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

It has been a drought period and hard to get the seed to take. We did some seeding + some noxious weed spraying.

7. What is the **total disturbed acreage** at years end? 25 acres

8. Briefly summarize mining and reclamation planned for the upcoming year.

We have probably disturbed all of the virgin ground we will for several years. We will continue mining in the area we have and start reseeding the dump areas again now that there appears to be moisture. Also with very little new disturbance in the areas ~~over~~ of burden piles we should start reclaiming them.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.

2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Carsten N. Mortensen

Title of Operator: Pres. Gen. Mgr.

Signature of Operator: Carsten N. Mortensen

Date: 1-8-93

jb
MR-AR